




SIGN MOUNTING HARDWARE ASSEMBLY

TOOLS NEEDED:
Socket Wrench 1/2"

Metalcraft uses 3/8" drill bits for drilling holes in the pole

Flat washers, nuts and bolts are all
18-8 stainless steel with a black oxide coating

- PARTS LIST EACH SET:
Generally, two sets are needed for each sign
- 1 - Bolt
 - 2 - Flat Washers
 - 1 - Cast/Curved Aluminum Washer
 - 1 - Nut



**Illustrations are not to scale*